

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/02/2021

Submitted Date:

09/04/2021

Document Number:

696104969

FIELD INSPECTION FORM
 Loc ID 414138 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 27742

Name of Operator: EOG RESOURCES INC

Address: 600 17TH ST STE 1100N

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Morgan, John		john.morgan@state.co.us	
,		dnr_cogccengineering@state.co.us	
Limongelli, Kristen	(303) 501-2132	kristen_limongelli@eogresources.com	Regulatory Administrator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413064	WELL	AC	09/01/2011	OBW	123-30585	Bevo 4-36 SWD	PA

General Comment:

This is a PLUGGED & ABANDONED WELL / CEMENTING inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing. Final plug.

Battery: Abandoned. ALL Equipment removed.

Abandoned Battery SE corner GPS coordinates: 40.967955 / -104.384042

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	Wellhead: w/ Master & casing valves removed.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 413064 Type: WELL API Number: 123-30585 Status: AC Insp. Status: PA**Cement**Cement ContractorContractor Name: IEC Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 1400'-700'-0'Cement Volume (sx): 152 sxsGood Return During Job: YESCement Type: Class GComment:

Workover Contractor: Peak Well Services Rig.

Cementing Contractor: IEC Services.

Reference:

Form 42 doc. #402790309. Notice of plugging start date: 08/30/2021. Approved.

Form 6 doc. #402675537. Notice of Intent to Abandon date: 07/28/2021. Approved.

Form 17 doc. #402778355. Bradenhead Test Report date: 08/10/2021. Approved.

Prior MIT. Form 21-MIT doc. #402293584. MIT date: 06/14/2018. Approved.

Final cement pumped.

Cut pipe and install temporary cap.

Secure site with iron panel fencing & high visibility safety markings.

Commence 5-day waiting period before final permanent cap is done.

9/02/21 RIH TAG@ 1400' 44 JTS POOH TO 700' 22 JTS PUMP 152 SXS OF CLASS G

CEMENT POOH ND BOPS TOP OFF WELL

DIG OUT AND CUT OFF.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/02/2021 at approximately 11:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: EOG RESOURCES INC Location Name: BEVO /4-36M Location ID: 414138 Well Name(s): Bevo 4-36 SWD. API: 05-123-30585. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Final plug. Battery: Abandoned. ALL Equipment removed. Abandoned Battery SE corner GPS coordinates: 40.967955 / -104.384042</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Final cement pumped. Cut pipe and install temporary cap. Secure site with iron panel fencing & high visibility safety markings. Commence 5-day waiting period before final permanent cap is done. Form 6N doc. #402675537 indicates Notice of Intent to Abandon date: 07/28/2021. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/04/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104970	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524282