

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2021

Submitted Date:

09/05/2021

Document Number:

696104975

**FIELD INSPECTION FORM**Loc ID 418967 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418971	WELL	PR	05/01/2020	OW	123-32081	Critter Creek 11-07H	PR

**General Comment:**

This is a WELL / BATTERY inspection.

Well(s): 1: Producing | PR.

Battery: Active.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron mesh panel.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Heater Treater surrounded by earth berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4		
Comment:	4 / 4: marked.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor. Controls crude oil tanks vapors. Pilots: ON.		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	Not in use. Inactive.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor drives pump jack.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Sales. Calibration card indicates calibration within last year. Last calibration: 05/19/2021. Active w/ production.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	At Battery site: 1: ECD scrubber. 1: Propane tank. Placards. 1: Electric power bank. 1: Line heater. Surrounded by protective shed. 1: Oil reycle pump. Surrounded by protective shed.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Surrounded by protective shed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		40.930683,-104.467737

Comment:

Corrective Action:

Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ produced H2O tank.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 418971 Type: WELL API Number: 123-32081 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/03/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 09/03/2021 at approximately 15:09 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: HIGHPOINT OPERATING CORPORATION  Location Name: Critter Creek /11-07H  Location ID: 418967  Well Name(s):  Critter Creek 11-07H.  API: 05-123-32081.  Location County: Weld County, Colorado  Weather: Partly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Producing   PR.  Battery: Active.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/05/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104976	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524308</a>