

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2021

Submitted Date:

08/31/2021

Document Number:

700600289**FIELD INSPECTION FORM**Loc ID 309123 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		rmack@ogrisop.com	<a href="#">All Inspections</a>
Santistevan, Vince		vsantistevan@ogrisop.com	<a href="#">All Inspections</a>
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	<a href="#">All Inspections</a>
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288298	WELL	PR	06/04/2007	GW	071-09112	GOLDEN EAGLE 29-6	EI
292688	PIT	AC	09/03/2008		-	GOLDEN EAGLE 29-06	AC

**General Comment:**[This is an environmental inspection only. Any corrective actions from previous inspections are still in effect.](#)[Produced water pit appears to contain oily waste. See corrective action.](#)

Inspected Facilities									
Facility ID:	288298	Type:	WELL	API Number:	071-09112	Status:	PR	Insp. Status:	EI
Facility ID:	292688	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 292688Lat: 37.144659Long: -104.913254Reference Point: SEOther: Length: Width: **Lining:**Liner Type: OtherLiner Condition: Comment: Unlined produced water pit appears to have oily waste in it. See attached photos.

Corrective Action

Operator shall sample liquid in pit for COGCC Table 915-1 Organic Compounds in Groundwater and TPH (C6-C36) and submit via Field Inspection Resolution Request (FIRR) in response to this inspection. Corrective Action date is for collecting samples.

Date: 09/06/2021**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402797715	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519880">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519880</a>
700600290	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519879</a>