

# Inspection Photos

API: 071-08482

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08482 | Date: 9/3/2021

## Inspection Photos



**Photo 1.** Facing west along the access road. There is insufficient BMP's along the road causing stormwater to flow down a long portion of the road which is causing erosion. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08482 | Date: 9/3/2021

## Inspection Photos



**Photo 2.** Stormwater is directed down the road causing erosion shown in previous photos. Stormwater should be diverted off the road shown at red arrow, The yellow arrow points to a piece of rebar stuck in the road which could puncture a tire.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08482 | Date: 9/3/2021

## Inspection Photos



**Photo 3.** Facing toward the location.

