

Inspection Photos

API: 071-07560

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 1. There is vehicle rutting along the road traveling to the location. The road needs to be maintained. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 2. Facing southwest along the access road. There are areas of erosion along the road. A hard hat was placed in the erosion channel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 3. Facing southeast along the access road. There is a low spot in the road where stormwater accumulates. This area needs to be repaired to allow proper drainage. Red arrow points to culverts that are not maintained to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 4. Likewise to previous photo. There is a low spot in the road where stormwater accumulates and vehicles are widening the road to avoid this area. This area needs to be repaired to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 5. There are noxious weeds along the roadside that need to be controlled. Red arrow points to Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 6. There is vehicle rutting along the road traveling to the location. The road needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 7. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 8. Facing toward the location. Areas of rutting at the location need to be repaired and stabilized. Production areas are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021

Inspection Photos



Photo 9. The insulation around the piping is degraded. The insulation debris needs to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 9/3/2021