

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

09/01/2021

Document Number:

688800971

FIELD INSPECTION FORM
 Loc ID 306991 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 7125

Name of Operator: BEEMAN OIL & GAS LLC

Address: 3401 QUEBEC ST SUITE 9105

City: DENVER State: CO Zip: 80207

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beeman, Bob		robertbeeman@msn.com	Owner
Galloway, Kelly		kgallowaywerc@gmail.com	
Fischer, Alex		alex.fischer@state.co.us	
Lawton, Lisa		lisa@beemanoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290406	WELL	PR	04/01/2021	OW	067-09363	GLADYS 2	EI
479276	OFF- LOCATION FLOWLINE	AC			-	Dump Line 33N12W	AC

General Comment:

On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #2. For the most recent field inspection report of this facility, please refer to document #693903586. The regional COGCC Reclamation Specialist was on site during this inspection.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign mounted to fencing around electrical supply equipment.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Ranger Pro herbicide container on pump jack skid.			
Corrective Action:	Comply with Rule 606.			Date: 09/15/2021
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Well head and surrounding area are stained with oil.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/01/2021
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil beneath truck load out valve on vertical AST at tank battery. Load out valve on horizontal tank is wet and stained with oil. Stained and wet soil beneath valve.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/01/2021
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	IGNITOR/COMBUSTOR			
Comment:	"T" post and hog wire fence around combustor and electrical supply panel.			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	Electric motor.			
Corrective Action:				Date:
Type: Pump Jack	# 1			

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical supply panel.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Combustor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425	
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	252	
Other (Type)	Horizontal skid mounted tank.	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425	
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

AirsID

API Number

AirsID

Wells Served By Facilities Above

API Number

067-09099

067-09363

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290406	Type:	WELL	API Number:	067-09363	Status:	PR	Insp. Status:	EI
Facility ID:	479276	Type:	OFF-	API Number:	-	Status:	AC	Insp. Status:	AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #2. For the most recent field inspection report of this facility, please refer to document #693903586. The regional COGCC Reclamation Specialist was on site during this inspection.</p> <p>During this inspection a container labeled herbicide was being stored on the pump jack skid.</p> <p>Stained soil was observed around the well head and beneath the truck load out valves on the ASTs at the tank battery.</p>	hughesjo	09/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402800194	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521898
688800972	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521884