

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

09/01/2021

Document Number:

688800973

## FIELD INSPECTION FORM

 Loc ID 306948 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 7125  
 Name of Operator: BEEMAN OIL & GAS LLC  
 Address: 3401 QUEBEC ST SUITE 9105  
 City: DENVER State: CO Zip: 80207
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 14 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beeman, Bob		robertbeeman@msn.com	Owner
Galloway, Kelly		kgallowaywerc@gmail.com	
Lawton, Lisa		lisa@beemanoil.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282621	WELL	PR	08/01/2020	OW	067-09099	GLADYS 1	EI
479272	OFF-LOCATION FLOWLINE	AC	01/28/2021		-	Dump Line 14NENE	EI

**General Comment:**

On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #1. For the most recent field inspection report of this facility, please refer to document #693903586. The COGCC regional Reclamation Specialist was on site during this site visit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted near well head.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Sign posted at shared tank battery.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil near well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>10/01/2021</u>
Crude Oil	Tank	<= 1 bbl	
Comment:	See corrective actions on Inspection Document #688800971 regarding stained soil at shared tank battery.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>10/01/2021</u>
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	Combustor and electrical supply panel have fencing.		
Corrective Action:			
Date:			
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Electrical supply panel.		
Corrective Action:			
Date:			
Type: Ancillary equipment	# 1		
Comment:	Combustor		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	252
Other (Type)	Horizontal skid mounted.

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.109286,-108.110425
Comment:	Gladys #1 and #2 shared tank battery facility ID #479276.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
067-09099

**AirsID**

API Number	AirsID
------------	--------

067-09363

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 282621 Type: WELL API Number: 067-09099 Status: PR Insp. Status: EI

Facility ID: 479272 Type: OFF- API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Beeman Oil and Gas LLC Gladys #1. For the most recent field inspection report of this facility, please refer to document #693903586. The COGCC regional Reclamation Specialist was on site during this site visit. Inspection Document #688800971 lists corrective actions regarding stained soil at the shared tank battery. Stained soil was observed around the well head during this inspection.</p>	hughesjo	09/01/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402800213	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521929">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521929</a>
688800974	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521928</a>