

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2021

Submitted Date:

09/01/2021

Document Number:

700900654

FIELD INSPECTION FORMLoc ID 320030 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J. B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202316	WELL	SI	06/01/2018	GW	001-07721	CHAMPLIN 248 AMOCO A 3	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Inadequate berms or unmaintained berms around tank(s)				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 9/30/2021. See attached photo # 4				Date: 09/30/2021

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.835842,-104.521539
Comment: Stained soil on east side of tanks .					
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 9/30/2021 to remove stained soil. See attached photo #5 & 6					Date: 09/30/2021

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Inadequate berms or unmaintained berms around tank(s)				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 9/30/2021. See attached photo # 4				Date: 09/30/2021

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
001-07721		

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 202316 Type: WELL API Number: 001-07721 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday August 19, 2021 at approximately 10:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Champlin 248 Amoco A3, Renegade oil & Gas Company, at API # 001-07721 in Adams County Colorado.</p> <p>While there, I observed a Shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Inadequate berms or unmaintained berms around tank(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 9/30/2021. See attached photo # 4</p> <p>Stained soil on east side of tanks . Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 9/30/2021 to remove stained soil. See attached photo #5 & 6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	09/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402800101	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521717
700900655	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5521710