

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

09/02/2021

Document Number:

688800982**FIELD INSPECTION FORM**Loc ID 325151 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	<a href="#">All Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	
Williford, Hearne	918-712-8828	hwilli@swbell.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214134	WELL	SI	02/01/2020	OW	067-05446	DYE-HARD 1	EI

**General Comment:**

On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Dye Hard #1. For the most recent field inspection report of this facility, please refer to document #693903144.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	Free standing sign near AST at tank battery.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near pump jack.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weeds present throughout secondary containment berm.			
Corrective Action:	Comply with Rule 606.			Date: 09/09/2021
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Guard fencing present.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment			# 1	corrective date
Comment:			Electrical supply equipment.	
Corrective Action:			Date:	
Type: Prime Mover			# 1	
Comment:			Electric motor.	
Corrective Action:			Date:	
Type: Pump Jack			# 1	
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.109263,-108.110056

Comment:	
----------	--

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate

Comment:	Weeds present throughout secondary containment berm.
----------	--

Corrective Action:	Comply with Rule 606.	Date:	09/09/2021
--------------------	-----------------------	-------	------------

**Wells Served By Facilities Above**

API Number
067-05446

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for blow down drum.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 26, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Dye Hard #1. For the most recent field inspection report of this facility, please refer to document #693903144. Weeds present throughout secondary containment berm.	hughesjo	09/02/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402801727	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523229">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523229</a>
688800983	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523228">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523228</a>