

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402574970

Date Received:

01/14/2021

**FIR RESOLUTION FORM**

Overall Status: FRQ

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10734

Name of Operator: HIGH RIVER RESOURCES OPERATING LLC

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Amy Archuleta

Phone

505-320-6917

Email

aarchuleta@highriverllc.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 693902730

Inspection Date: 01/11/2021

FIR Submit Date: 01/13/2021

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: HIGH RIVER RESOURCES OPERATING LLC

Company Number: 10734

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

**LOCATION - Location ID: 311948**

Location Name: IGNACIO 33-7-N33N7W Number: 32SWSW County: LA PLATA

Qtrqr: SWS Sec: 32 Twp: 33N Range: 7W Meridian: N  
W

Latitude: 37.056660 Longitude: -107.637790

**FACILITY - API Number: 05-067- -00 Facility ID: 215711**

Facility Name: IGNACIO 33-7 Number: 14-32

Qtrqr: SWS Sec: 32 Twp: 33N Range: 7W Meridian: N  
W

Latitude: 37.056660 Longitude: -107.637790

**CORRECTIVE ACTIONS:**

2 ☒ CA# 145845

Corrective Action: -Stormwater controls need to be installed to stabilize erosion within the project area. Corrective action is back-dated to original corrective action date (5/17/2019) to document duration of non-compliance.

Date: 05/17/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Inspection Document: 402574970

As noted on the Inspection, this inspection was submitted to the previous owner (Enervest) in 2019. As the new

Operator Comment: operator, we were unaware this work was not complete. That should be noted on this inspection as well for documentation of compliance.  
This location is on a shared pad with Red Willow Production Company. They have two wells on this location. The Ignacio 33 7 #32-4 API: 05-067-08503 and the Ignacio 33 7 #32-5 API: 067-09198. After reviewing the site, High River believes this should be a joint effort. We are unclear on how you determine which operator is responsible for erosion issues on a shared pad. RWPC's location has not been inspected since 2014. I have attached an aerial photo for reference of equipment ownership and erosion issues.

COGCC Decision: **Not Approved**

COGCC Representative: On a shared location it is the responsibility of all operator's to ensure compliance. COGCC does not maintain jurisdiction over the Red Willow operations at this location. High River is responsible for all corrective actions on their locations including any that were not addressed by a previous operator.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed:

Title: Regulatory Supervisor

Date: 1/14/2021 12:35:43 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402574970	FIR RESOLUTION SUBMITTED
402575061	Aerial View

Total Attach: 2 Files