

Well Name : Price 13-25

API # : 115-06056



Photo 1: View of sign at the separator.



Photo 2: View of separator and vegetation around it.

Well Name : Price 13-25

API # : 115-06056



Photo 3: View of location entrance from CR with separator and vegetation around it.



Photo 4: Additional view of location entrance from CR with separator, vegetation, and pumping unit in background.

Well Name : Price 13-25

API # : 115-06056



Photo 5: View of trash and rubbish inside separator house.



Photo 6: View of what appears to be old pit site in pasture between well site and separator facility.

Well Name : Price 13-25

API # : 115-06056



Photo 7: View of wellhead sign at well site.



Photo 8: View of wellhead and tree. Well actively venting at packing/cap. Valves were found closed at time of inspection.

Well Name : Price 13-25

API # : 115-06056



Photo 9: View of packing and cap.



Photo 10: View of pumping unit and vegetation inside the fencing. Polish rod is attached to the bridge.

Well Name : Price 13-25  
API # : 115-06056



Photo 11: View of electric prime mover and vegetation inside fencing.



Photo 12: View of control box and vegetation inside fencing.

Well Name : Price 13-25

API # : 115-06056



Photo 13: View of disconnected dryer vessel laying inside pumping unit fencing.



Photo 14: View of disconnected/empty 55 gallon drum on skid mount inside pumping unit fencing.

Well Name : Price 13-25

API # : 115-06056



Photo 15: View of Pumping unit, polish rod, and bridle. Note vegetation inside fencing.



Photo 16: View of well site. One of four located anchors with markers down at time of inspection.