

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2021

Submitted Date:

09/09/2021

Document Number:

697601544

FIELD INSPECTION FORMLoc ID 311511 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
inspections, All		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446223	TANK BATTERY	AC	08/20/2008		-	PLATTE 26-2	EI
446224	TANK BATTERY	AC	06/17/2016		-	PLATTE 26-2	EI

General Comment:

Operator staff on site at time of inspection to discuss progress of remediation project 9302 with COGCC staff.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:	removed as part of facility reconstruction					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: removed as part of facility reconstruction						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
123-16618
123-32337

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities								
Facility ID:	446223	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	446224	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: remediation project 9302 (ongoing).
Operator has removed crude oil and produced water storage vessels and as part of site investigation and remediation project has removed majority of impacts that were present below tanks and above CLaymax liner.

Corrective Action: submit quarterly update for third quarter activities within 90 days of inspection

Date: 12/08/2021

Emission Control Burner (ECB): YES

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601545	area where crude and PW tanks removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527518
697601546	separators and emission control device	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527519