

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2021

Submitted Date:

09/09/2021

Document Number:

697601550

FIELD INSPECTION FORM

Loc ID 467175 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467173	TANK BATTERY	AC	09/03/2019		-	KPK Tank Battery 28SWNE	EI

General Comment:

inspection of production facility that serves four wells. Wells not inspected in this report

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	BATTERY				
Comment:	adequate - each well served by battery identified by name				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	on battery sign				Date:
Corrective Action:					Date:
Good Housekeeping:					
Type	DEBRIS				
Comment:	concrete debris/trash from removal of concrete vault PW vessel remain on site at edge of earthen berm around crude tanks as shown in attached photo				
Corrective Action:	Comply with Rule 606 by removing trash/debris from location				Date: 09/07/2021
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
Crude Oil		<= 1 bbl			
Comment:	stained soils under meter housing as shown in attached photo				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. by removing stained soil.				Date: 10/09/2021
Crude Oil	Tank	<= 1 bbl			
Comment:	stained soils near crude tanks as shown in attached photos				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. by removing stained soil.				Date: 10/09/2021
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Emission Control Device	# 1				corrective date
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	buried concrete vault removed as part of project 14115 and spill 476532				

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.111513,-104.000000

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-10170
123-10149
123-09367
123-09162

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 467173 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601551	crude tanks and battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527607
697601552	hydrocarbon stained soils at crude tank to south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527608
697601553	hydrocarbon stained soils at crude tank to north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527609
697601554	hydrocarbon stained soils under meter housing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527610
697601555	separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527611
697601556	emission control device	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527612
697601557	pieces of concrete vault (unused equipment - junk)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527613