

Inspection Photos
Operator: Simcoe
API: 067-08689
Date: 9/7/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the access road, surface is recently graded, culverts and ditches are maintained.



Photo 3. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass, rubber rabbitbrush, and fourwing saltbush.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of reference area comprised of pinyon and juniper woodland with yucca, sagebrush, prickly pear, and Indian ricegrass.