

Inspection Photos
Operator: Maralex
API: 067-09350
Date: 9/7/2021



Photo 1. View of the project area from the well pad entrance facing center. Sign needs to be repaired.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is largely kochia, similar to surrounding grazed pasture.



Photo 3. View of the southern project area from the southeastern corner facing westward. Adjacent well pad visible.



Photo 5. View of reference area comprised of grazed pasture.