

Inspection Photos  
Operator: Simcoe  
API: 067-07589  
Date: 9/7/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is comprised of grazed grasses such as western wheatgrass and kochia.





Photo 3. View of the northern project area facing westward. Well pad grading and berm construction is in process. Disturbed soils outside of the working area need seeding after work is completed.



Photo 4. View of reference area comprised of grazed pasture.