

Inspection Photos
Operator: Simcoe
API: 067-08507
Date: 9/7/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is comprised of blue grama, western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of erosional channel in the southern project area where stormwater flows around cobbles and continues to erode channel.




Photo 5. View of headcut where erosional channel begins to erode in the southern project area. Headcut needs long-term stabilization.



Photo 6. View of reference area comprised of sagebrush shrubland with understory of James galleta, blue grama, and snakeweed.