

Inspection Photos

Operator: Dixie Mclane Trust
API: 067-06049
Date: 9/7/2021



Photo 1. View of the well head and well sign facing southward.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, and James galleta.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised of sagebrush shrubland with understory of James galleta, blue grama, and snakeweed.