

Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 9/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 1. The area of erosion has been repaired at Lat/Long:37.66008, -105.18761. This area also needs to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 2. The road had been regraded traveling to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 3. Facing northwest toward the location. A drill rig was on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 4. Facing toward the bermed area around the tank where stained soil was observed. There is still stained soils observed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 5. Facing northwest at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021

Inspection Photos



Photo 6. The oil staining near the tanks has not been cleaned up since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 9/9/2021