

Inspection Photos

API: 055-06105

Operator: OXY USA INC

Inspection Date: 9/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 9/9/2021

Inspection Photos



Photo 1. Facing southeast ascending the hill toward the location. There are rock check dams installed along the roadside. Some of the check dams will need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 9/9/2021

Inspection Photos



Photo 2. Facing southeast ascending the hill toward the location. There are rock check dams installed along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 9/9/2021

Inspection Photos



Photo 3. Facing northwest at the location. There is various unused equipment stored in this area which has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 9/9/2021

Inspection Photos



Photo 4. There were noxious weeds observed in areas of the location. There is weeds along the cut slope shown and red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 9/9/2021