

Inspection Photos

9/09/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 324288

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



September 9, 2021



September 9, 2021
39.52677903N 108.22914961W

Photo 1: Photos show frac tanks being stored on the northeast end of the Location. Equipment is not needed for production and requires removal.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 2: Photos taken from the fill slopes on the west end of the Location. Photos show BMPs to protect and stabilize the slopes, and manage runoff are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 3: Photos provide example of various trash debris observed on areas north of the Location (photo left), and improperly stored within the secondary containment.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



September 9, 2021
39.52709926N 108.22933901W



September 9, 2021
39.52710274N 108.22934284W

Photo 4: Photos show trash debris observed on the northwest end of the tank battery.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 5: Photos provide examples of tanks on the Location with missing, or inadequate labeling information. Safety labeling is needed in order for COGCC Staff to properly identify contents within a container; if staff is unable to identify contents, staff is unable to accurately assess whether or not container is used to store, treat or otherwise handle hazardous material.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 6: Photos provide examples showing that wildlife protection devices are missing or insufficient at several secondary containment BMPs.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 7: Photos provide examples showing that wildlife protection devices are missing or insufficient at several secondary containment BMPs.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 8: Photo taken from the containment BMP for the tank in left-photo 6. Photo shows multiple punctures observed at the base of the BMP.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 324288



Photo 9: Photo taken from the interim areas on the north end of the Location. Vegetation appears to be progressing towards 1003 standards.