

# Inspection Photos

9/09/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 324288

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC


Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



**Photo 1:** Photos show example of the interim areas of the Locaiton. At least 4 growing seasons have passed since interim work was performed. Photos show reclamation is not progressing towards an 80% uniform, desirable perennial vegetative establishment to that of the reference are. Photo also shows soils on the interim areas are subsoils; topsoil has not been placed onto the majority of interim areas.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



**Photo 2:** Photo taken from the interim areas on the northeast end of the Location. Photo shows interim areas in the foreground where topsoil was not replaced, and interim areas in the background where topsoil was replaced.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



**Photo 3:** Photos shows example of the cut slopes, where BMPs to protect and stabilize the slopes are missing or insufficient on the Location.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



September 9, 2021



September 9, 2021  
39.52439399N 108.22547027W

**Photo 4:** Photos shows erosion degradation due to runoff observed to the west of the tank battery.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



**Photo 5:** Photos show tear observed in the liner on the north side of the tank battery



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 324288



**Photo 6:** Photos shows control measures are missing or insufficient to protect and stabilize the fill slopes, and manage runoff on the northwest end of the Location.