

Inspection Photos
Operator: Enduring
API: 067-07914
Date: 9/9/2021



Photo 1. View of the project area from the southeastern corner facing center.




Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, and crested wheatgrass. Dense Russian thistles observed on the edges of the working area.




Photo 3. View of Russian thistle debris within the southeastern project area.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of blue grama, western wheatgrass, snakeweed, and prickly pear.