

Inspection Photos  
Operator: Enduring  
API: 067-06692  
Date: 9/9/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, and smooth brome.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of blue grama, western wheatgrass, snakeweed, and prickly pear.