

Inspection Photos
Operator: Enduring
API: 067-08647
Date: 9/9/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of erosional channel on the well pad (left) and cobble BMP eroded and displaced on the fill slope (right).



Photo 3. View of sediment deposition within the eastern sediment trap, largely full and needing maintenance.



Photo 4. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing in portions of the fill slopes with rubber rabbitbrush, sand dropseed, and crested wheatgrass. Other portions remain bare and eroding and need spot seeding and stabilization.



Photo 5. View of the reference area comprised of rubber rabbitbrush, western wheatgrass, smooth brome, and sagebrush.