

Inspection Photos
Operator: Enduring
API: 067-07636
Date: 9/9/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, and rubber rabbitbrush.



Photo 3. View of erosional channel forming on the well pad and flowing down the access road (facing upslope).



Photo 4. View of erosional channel shown in Photo 2, where it flows downslope eroding the access road surface and flowing off of the project area.



Photo 5. View of cobble BMPs along the southern project area that are full of sediment and not functioning, or adequate for this area. .



Photo 6. View of the reference area comprised of pinyon and juniper woodland with yucca, mountain mahogany, purple threeawn, and blue grama.