

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402786825

Date Received:

09/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Andrew Price

918-965-0044

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903531

Inspection Date: 08/06/2021

FIR Submit Date: 08/13/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326352

Location Name: HERRERA GAS UNIT A- Number: 20NENW County: LA PLATA  
N33N8W

Qtrqtr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N

Latitude: 37.093120 Longitude: -107.745160

FACILITY - API Number: 05-067- -00 Facility ID: 216287

Facility Name: HERRERA GAS UNIT A Number: 4

Qtrqtr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N

Latitude: 37.093120 Longitude: -107.745160

CORRECTIVE ACTIONS:

1 CA# 154806

Corrective Action: -Gravel, fill, and sediment discharged from the project area needs to be removed and properly managed. Revegetation is required if desirable vegetative cover is damaged as a result of material discharge. Corrective action date: 9/15/2021.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 09/10/2021

Operator Comment: Cleaned sediment from diversion ditches, Installed rock run downs and check dams. Removed rocks and gravel from the road and the sediment and gravel discharged from the project area, bare ground was roughened and reseeded.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 154807

Corrective Action: -Stormwater (ie: BMPs) and erosion controls (ie: erosion control blanket, hydromulch, etc.) need to be installed to stabilize erosion and prevent sediment discharge within the project area, no later than 9/15/2021. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 09/10/2021

Operator Comment: Cleaned sediment from diversion ditches, Installed rock run downs and check dams. Removed rocks and gravel from the road and the sediment and gravel discharged from the project area, bare ground was roughened and reseeded.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 9/14/2021 3:16:17 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402811273	Herrera Gas Unit A 4 9-15-21 (693903531) remedial report
-----------	--

Total Attach: 1 Files