

Inspection Photos
Operator: Petrox
Facility: 471016
Date: 9/13/2021



Photo 1. View of the project area from the facility entrance facing center.



Photo 3. View of the northern project area from the northwestern edge facing eastward. Revegetation is progressing in non-weedy areas with smooth brome.




Photo 2. View of spotted knapweeds growing along the northern edge of the project disturbance. Approximately 3000 individuals observed in infestation.




Photo 4. View of more spotted knapweeds growing at facility entrance.



Photo 5. View of the reference area comprised of mixed grass field, with ponderosa pine forest, and western wheatgrass, smooth brome, serviceberry, and gambel oak in the understory.