

UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT-62S102W 26SWSE Location # 314307



Battery sign installed at tank battery.



Weeds have been addressed.



**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Sink hole in shoulder of access road. Just south of
DTU 1056 entrance.**

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Sink hole in shoulder of access road. Just south of
DTU 1056 entrance.**

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Sink hole in shoulder of access road. Just south of
DTU 1056 entrance.**

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Erosion rills in roadway.



Storm water movement of sediment on access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road and narrowing roadway.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Storm water erosion of access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Intersection of CR 116 and access to DTU 1001 and
DTU 1056**

