

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2021

Submitted Date:

09/16/2021

Document Number:

701101946

FIELD INSPECTION FORMLoc ID 314307 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 760 HORIZON DRIVE STE 400

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228287	WELL	PR	06/01/2002	GW	103-05113	DRAGON TRAIL UNIT	PR

General Comment:**COGCC Follow Up Inspection Report Summary**

Follow up to 7/13/2021 inspection # 701101731

Corrected action item(s)

- Road was bladed.
- Battery sign installed at tank battery.
- Weeds have been addressed.
- No visible gas line exposed along access road.

During this inspection the following compliance issues were observed:

- Sink hole in shoulder of access road. Just south of DTU 1056 entrance.

The following uncorrected compliance issue were observed:

- Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek. Shoulder of road is washing away. No evidence of storm BMPs on access road.
- A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Road was bladed.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No api# on well tag/sign.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign installed at tank battery.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911 970-693-6021	
Corrective Action:		Date:

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have been addressed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	<100 BBLS	Open Top		,	

Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected FacilitiesFacility ID: 228287 Type: WELL API Number: 103-05113 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Flowline

#1 Type: Sales Line

of Lines

Flowline DescriptionFlowline Type: Sales LineSize: 4"Material: Carbon Steel

Variance:

Age:

Contents: Natural GasIntegrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Flowline has been covered with earthen material.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			no evidence of ditches
Compaction						
		Compaction	Fail			Road is soft in areas and signs of erosion.
Berms						
		Gravel	Fail			
Ditches						
		Culverts	Fail			

Comment: Sink hole in shoulder of access road. Just south of DTU 1056 entrance. Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek. Shoulder of road is washing away.
No evidence of storm BMPs on access road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101953	Inspection 701101946 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533396