

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/16/2021

Submitted Date:

09/16/2021

Document Number:

695104834

**FIELD INSPECTION FORM**
 Loc ID 309510 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
GEE, GREG	903-987-0353	ggee@ogrisop.com	<a href="#">All Inspections</a>
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	<a href="#">All Inspections</a>
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297297	WELL	SI	05/01/2021	GW	071-09632	APACHE CANYON 04-04	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	PHOTO 8 & 9: CULVERT ON ROW TO LOCATION IS COMPLETELY BARRIED ON UPGRADE SIDE OF ROW.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C.	Date:	09/23/2021
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			
Date:			
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNUSED EQUIPMENT (NORTH SOUND WALL FOR COMPRESSOR HAS FALLEN DOWN). PHOTO 4: SOUTH SOUNDWALL FOR COMPRESSOR APPEARS TO BE FALLING DOWN. MAINTENANCE IS REQUIRED.		
Corrective Action:	COMPLY WITH RULE 606. REPAIR OR REMOVE UNUSED EQUIPMENT.	Date:	09/23/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil		<= 1 bbl	
Comment:	PHOTO 5, 6 & 7: APPEARS TO BE AN OIL SPILL AROUND COMPRESSOR.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Contact COGCC EPS staff. (NOTE: COMPRESSOR WILL HAVE TO BE MOVED TO REMOVE OR TREAT IMPACTED SOIL UNDERNEATH COMPRESSOR).		Date: 09/17/2021
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:			
Corrective Action:	Date:		
Type: Compressor	# 1		
Comment:	INSIDE SOUND WALLS		
Corrective Action:	Date:		
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:	Date:		
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	ALL HAVE MARKERS		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		,
Comment:	PHOTO 11: NFPA STICKER IS CRACKED AND FALLING APART, TANK CAPACITY NOT POSTED.				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 10/16/2021

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	N/A			
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 297297 Type: WELL API Number: 071-09632 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: WELL SHUT IN MAY 2021

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 01/29/2020

Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Fail			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: PHOTO 8 & 9: CULVERT ON ROW TO LOCATION IS COMPLETELY BARRIED ON UPGRADE SIDE OF ROW.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 09/23/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 300257 Lat: 37.117000 Long: -104.901400

Reference Point: SE Other: \_\_\_\_\_ Length: 80 Width: 40

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife Fencing Condition: Inadequate

Comment: PHOTO 10: FENCING AROUND PIT IN DISREPAIR.

Corrective Action: \_\_\_\_\_

Date: 09/23/2021

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	300257	1841330	
	300257	1841330	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104835	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533788">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533788</a>