


**Inspection Photos**  
**Location Name: Horth 41-15-1**  
**Location ID:**




**Pic 1 stained soil from recent workover**



**Pic 1 Tubing gauge**



**Inspection Photos**  
**Location Name: Horth 41-15-1**  
**Location ID:**



**Pic 3 casing gauge**



**Pic 4 bradenhead unaccusable due to broken threads in  
needle valve**

