

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2021

Submitted Date:

09/16/2021

Document Number:

699503176

FIELD INSPECTION FORMLoc ID 320112 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
		jm@p3petro.com	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202658	WELL	PR	05/01/2019	GW	001-08063	HORTH 41-15 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Stained soil by wellhead see pic 1

Corrective Action: Comply with COGCC housekeeping rules.

Date: 10/16/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Plunger automation

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202658 Type: WELL API Number: 001-08063 Status: PR Insp. Status: PR

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well is TA, 1 join is in wellbore to install wellhead

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/29/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Bradenhead test was unable to be performed due to broken threaded parts inside of threaded bull plug. Unable to document pressure through a gauge reading. Bradenhead inaccessible or not visible

09/26/2021

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 9/16/21 at approximately 1230 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Horth 41-15-1 Company Name- P3 API- 05-001-08063 In Adams County Colorado. While there, I observed TA well During this inspection the following possible compliance issues were observed: Bradenhead inaccessible or not visible Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) 9/26/21 Stained soil by wellhead see pic 1 Comply with COGCC housekeeping rules. 10/16/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Previous inspection corrective actions may still be valid. This is a summary of inspection report.</p>	medinaj	09/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503177	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533930