

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2021

Submitted Date:

09/17/2021

Document Number:

700703247

FIELD INSPECTION FORMLoc ID 334801 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199993	WELL	PR	05/08/2000	GW	045-07408	BENZEL 1-9	PR
256350	WELL	PR	11/10/1999	GW	045-07445	BJM 6-11 (I 1)	PR
256351	WELL	PR	09/14/2000	GW	045-07446	BENZEL 1-16(I1)	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 9/16/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus I1, at Location # 334801 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Three horizontal unit separators includes 3 glycol storage tank, approximately 33" x 34" x 118" = 13.64 BBLS each and two vertical unit separators includes 2 glycol storage tank, approximately 71" x 48" x 192" = 67.44 BBLS each, storage vessel contains no labeling to specify capacity or chemical hazard information.

2. Holes in tank battery containment

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Three horizontal unit separators includes 3 glycol storage tank, approximately 33" x 34" x 118" = 13.64 BBLS each and two vertical unit separators includes 2 glycol storage tank, approximately 71" x 48" x 192" = 67.44 BBLS each, storage vessel contains no labeling to specify capacity or chemical hazard information.			
Corrective Action:	Comply with rule 605.h.			Date: 12/17/2021
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Horizontal Heated Separator	# 3			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:				

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Holes in tank battery containment			
Corrective Action:	Install or maintain liner material to ensure spill or released materials will be maintained with containment structure.			Date: 10/22/2021

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 199993 Type: WELL API Number: 045-07408 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 256350 Type: WELL API Number: 045-07445 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 256351 Type: WELL API Number: 045-07446 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703257	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5534430