

Final Reclamation Inspection

August 26, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 309667

Inspection Document #: 7019000086

Weld County, CO

NWSW Section 33 T5N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hergenreder 13-33U
Location ID: 309667




Photo 1. 2016 aerial imagery of the well head, tank battery, access road and reference area.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 2. Well Pad overview photo taken at ground level from northern edge of tank battery looking south down access road. Photo shows alfalfa crop within well head disturbance pad appears consistent with the rest of the crop field.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 3. Ground photos taken from the middle of the well head. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 4. Ground photos taken from the middle of the well head. Left photo facing south, right photo facing west.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 5. Overview photo of tank battery taken at ground level from the eastern edge of the disturbance pad, looking west. Photo shows Gravel remains on site with dispersed kohia and puncture vine growth. Historical imagery shows that the pre disturbance area was used to grow hay crop (see photo 6). Note: staged hay is just outside of the tank battery disturbance area.

Inspection Photos
Location Name:Hergenreder 13-33U
Location ID: 309667



Photo 6. 2016 aerial imagery on the left and 2006 imagery on the right (tank battery highlighted in red). Photo shows tank battery was used to harvest hay crop pre disturbance.