

Inspection Photos

API: 071-07766

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 1. Facing northeast along the access road. The road is not stabilized and there is erosion channels along the road. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 2. The road is not stabilized and there is erosion channels along the road. Red arrow points to hard hat for scale. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 3. Facing northeast further along the access road. The road is not stabilized and there is erosion channels along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 4. Facing back where the road turns down the hill side into the canyon. The side of the road is not stabilized in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 5. There is erosion occurring along the side of the road and culverts are filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 6. The arrow points to a culvert which is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 7. Facing northwest along the access road descending into the canyon. There is erosion along the road all the way down to the canyon bottom.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 8. Facing northwest along the access road descending into the canyon. There is erosion along the road all the way down to the canyon bottom.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 9. The road crosses the canyon bottom which creates a dam across the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 10. Facing east along the access road. It appears erosion has occurred along the road and stormwater is not diverted toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 11. Facing southeast toward the location. There is a culvert that remains at red arrow. The location has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021

Inspection Photos



Photo 12. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2021