

Red Willow Provided as Courtesy

Reportable Release Photographic Documentation

Middle Pad 7F – 9/7/21 (2021-0025)

Looking North: Seal failed within the transfer pump allowing water out.



Looking North: Impacted area in diversion ditch after a water truck pulled the standing water.



Looking West: Impacted area outside of the pump building.



Looking South: Terminus of release looking back toward the pump building.



Looking Northwest: Impacted area outside of pump building looking towards the terminus. Water truck was pulling standing water where possible.

