

Inspection Photos
Operator: Simcoe
Facility: 067-09938
Date: 9/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of Russian thistles on the well pad and debris around the wellhead. Living R. thistles will soon break and become debris.



Photo 5. View of the reference area, comprised of sagebrush shrubland with open pinyon and juniper woodland and blue grama, squirreltail, four o'clock, and goldenaster in the understory.



Photos 6-8. View of closed gates after leaving location.