

Inspection Photos  
Operator: Simcoe  
Facility: 067-06684  
Date: 9/16/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing southward. Revegetation is progressing with rubber rabbitbrush and western wheatgrass in a grazed vegetative condition.



Photo 3. View of the eastern project area from the northeastern corner facing northward.



Photo 4. View of the reference area, comprised of open field, largely in a grazed vegetative condition.