

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/13/2021

Submitted Date:

09/15/2021

Document Number:

700703231

FIELD INSPECTION FORM
 Loc ID 335044 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211321	WELL	PR	12/25/1996	GW	045-07081	FEDERAL RU 34-6	PR
301529	WELL	PR	02/28/2011	GW	045-18171	FEDERAL RU 32-6	PR
301530	WELL	PR	12/08/2011	GW	045-18172	FEDERAL RU 443-6	PR
301531	WELL	PR	03/31/2011	GW	045-18173	FEDERAL RU 344-6	PR
301532	WELL	PR	11/01/2011	GW	045-18174	FEDERAL RU 333-6	PR
439587	WELL	PR	12/03/2015	OW	045-22537	Federal RU 33-6	PR
439593	WELL	PR	12/03/2015	OW	045-22543	Federal RU 533-6	PR
439594	WELL	PR	12/03/2015	OW	045-22544	Federal RU 43-6	PR
439596	WELL	PR	11/30/2015	OW	045-22546	Federal RU 544-6	PR
439599	WELL	PR	11/08/2015	OW	045-22549	Federal RU 434-6	PR
439600	WELL	PR	12/03/2015	OW	045-22550	Federal RU 332-6	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 9/13/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RU 34-6, at Location # 335044 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Staining near well heads.
2. Lack of bull plugs/caps at load out lines.
3. Three quad unit horizontal separators includes four glycol storage tanks, approximately 174" x 34" x 41" = 25 BBLS x 6, storage vessels contain no labeling to specify capacity or chemical hazard information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Three quad unit horizontal separators includes six glycol storage tanks, approximately 174" x 34" x 41" = 25 BBLs x 6, storage vessels contain no labeling to specify capacity or chemical hazard information.			
Corrective Action:	Comply with rule 605.h		Date:	12/15/2021
Type	CONTAINERS			
Comment:				
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	OTHER			
Comment:	Staining near well heads			
Corrective Action:	Remove stained material		Date:	10/01/2021
Type	OTHER			
Comment:	Bull plugs/caps missing on load out lines			
Corrective Action:	Comply with rule 603.i.		Date:	10/01/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:				corrective date	
Type: Bradenhead	# 11				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 3				
Comment:	Chemical tanks in plastic containments				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 12				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	500 gallon methanol tank in metal containment				
Corrective Action:					Date:
Type: Plunger Lift	# 11				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 7				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					

Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	211321	Type:	WELL	API Number:	045-07081	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	301529	Type:	WELL	API Number:	045-18171	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	301530	Type:	WELL	API Number:	045-18172	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	301531	Type:	WELL	API Number:	045-18173	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	301532	Type:	WELL	API Number:	045-18174	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	439587	Type:	WELL	API Number:	045-22537	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	439593	Type:	WELL	API Number:	045-22543	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	439594	Type:	WELL	API Number:	045-22544	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	439596	Type:	WELL	API Number:	045-22546	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	439599	Type:	WELL	API Number:	045-22549	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	439600	Type:	WELL	API Number:	045-22550	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402812162	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5531547
700703236	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5531541