

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/20/2021

Submitted Date:

09/22/2021

Document Number:

700703264

FIELD INSPECTION FORM
 Loc ID 335883 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Thomson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287332	WELL	DG	05/14/2013	GW	103-10928	FREEDOM UNIT 197-31A1	DG
287333	WELL	DG	01/01/2012	GW	103-10927	FREEDOM UNIT 197-31A2	DG
287334	WELL	PR	06/01/2020	GW	103-10926	FREEDOM UNIT 197-31A4	PR
287335	WELL	DG	01/01/2012	GW	103-10925	FREEDOM UNIT 197-31A5	DG
287336	WELL	DG	05/14/2013	GW	103-10924	FREEDOM UNIT 197-31A6	DG
287337	WELL	DG	10/01/2012	GW	103-10923	FREEDOM UNIT 197-31A7	DG
287338	WELL	DG	05/14/2013	GW	103-10922	FREEDOM UNIT 197-31A9	DG
287339	WELL	DG	01/01/2012	GW	103-10921	FREEDOM UNIT 197-31A3	DG
287340	WELL	DG	09/26/2014	GW	103-10920	FREEDOM UNIT 197-31A8	DG
287341	WELL	DG	12/11/2012	GW	103-10919	FREEDOM UNIT 197-31A10	DG

General Comment:

COGCC Inspection Report Summary

On Monday 9/20/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Freedom Unit 197-31, at Location # 335883 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. One horizontal unit separators includes 1 glycol storage tank, approximately 109" x 44" x 38" = 18.78 BBLS each, storage vessel contains no labeling to specify capacity or chemical hazard information.

2. Lack of battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e		Date: 11/22/2021
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	1. One horizontal unit separators includes 1 glycol storage tank, approximately 109" x 44" x 38" = 18.78 BBLs each, storage vessel contains no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Comply with rule 605		Date: 12/22/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	287332	Type:	WELL	API Number: 103-10928 Status: DG Insp. Status: DG
Facility ID:	287333	Type:	WELL	API Number: 103-10927 Status: DG Insp. Status: DG
Facility ID:	287334	Type:	WELL	API Number: 103-10926 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	287335	Type:	WELL	API Number: 103-10925 Status: DG Insp. Status: DG
Facility ID:	287336	Type:	WELL	API Number: 103-10924 Status: DG Insp. Status: DG
Facility ID:	287337	Type:	WELL	API Number: 103-10923 Status: DG Insp. Status: DG
Facility ID:	287338	Type:	WELL	API Number: 103-10922 Status: DG Insp. Status: DG
Facility ID:	287339	Type:	WELL	API Number: 103-10921 Status: DG Insp. Status: DG
Facility ID:	287340	Type:	WELL	API Number: 103-10920 Status: DG Insp. Status: DG
Facility ID:	287341	Type:	WELL	API Number: 103-10919 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	287448	1433528	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703274	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5537900