

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2021

Submitted Date:

09/22/2021

Document Number:

696105036

**FIELD INSPECTION FORM**Loc ID 410100 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                              | Comment         |
|----------------|-------|------------------------------------|-----------------|
| ,              |       | NBL_DJBU_Inspections@nblenergy.com | All Inspections |
| Pesicka, Conor |       | conor.pesicka@state.co.us          |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 301973      | WELL | TA     | 05/15/2020  | OW         | 123-30148 | FAULK USX AB 21-16P | TA          |

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Abandoned. ALL equipment has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.551449 / -104.549991

Abandoned Centralized Battery formerly served 3 Location IDs.  
(420555, 410100, 410151).  
(Well(s): 3: Temporarily Abandoned | TA).

Follow-up to Field Inspection Report Doc. #696104139 dated 01/06/2021.

| Location   |  |        |  |                 |
|--|--|--------|--|-----------------|
| <b>Lease Road:</b>                                     |  |        |  |                 |
| Type   | Access   |        |  |                 |
| comment:   | Adequate   |        |  |                 |
| Corrective Action                                      | L  |        |  | Date:           |
| Overall Good: <input type="checkbox"/>                 |  |        |  |                 |
| <b>Signs/Marker:</b>                                   |  |        |  |                 |
| Type   | WELLHEAD   |        |  |                 |
| Comment:   |  |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| Emergency Contact Number:                              |  |        |  |                 |
| Comment:   | <p>Prior insp: Invalid Emergency number posted at wellsite. Refer to Prior Rule 210.b. (1,2). Current Rule 605.d.<br/> Post valid Emergency number at wellsite. Comply w/ Prior Rule 210.b. (1,2). Current Rule 605.d.<br/> Corrective Action date: 04/06/2021.</p> <p>This insp:<br/> * Valid Emergency Number NOW posted at wellsite.<br/> See photos #1, 2.</p> |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| Overall Good: <input type="checkbox"/>                 |  |        |  |                 |
| <b>Spills:</b>   |  |        |  |                 |
| Type   | Area   | Volume |  |                 |
| In Containment: No                                     |  |        |  |                 |
| Comment: <input type="text"/>                          |  |        |  |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |  |                 |
| <b>Fencing/:</b>                                       |  |        |  |                 |
| Type   | WELLHEAD   |        |  |                 |
| Comment:   | Iron panel.  |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| <b>Equipment:</b>                                      |  |        |  |                 |
| Type: Gas Meter Run                                    | # 0  |        |  | corrective date |
| Comment:   | Battery Abandoned. Equipment removed.  |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| Type: Plunger Lift                                     | # 1  |        |  |                 |
| Comment:   |  |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| Type: Horizontal Heated Separator                      | # 0  |        |  |                 |
| Comment:   | Battery Abandoned. Equipment removed.  |        |  |                 |
| Corrective Action:                                     |  |        |  | Date:           |
| Type: Bradenhead                                       | # 1  |        |  |                 |
| Comment:   | Appears plumbed to surface.  |        |  |                 |

|                               |                                       |       |  |
|-------------------------------|---------------------------------------|-------|--|
| Corrective Action:            |                                       | Date: |  |
| Type: Emission Control Device | # 0                                   |       |  |
| Comment:                      | Battery Abandoned. Equipment removed. |       |  |
| Corrective Action:            |                                       | Date: |  |

**Tanks and Berms:**

|                    |                                       |          |      |         |        |  |
|--------------------|---------------------------------------|----------|------|---------|--------|--|
| Contents           | #                                     | Capacity | Type | Tank ID | SE GPS |  |
| PRODUCED WATER     | 0                                     |          |      |         | ,      |  |
| Comment:           | Battery Abandoned. Equipment removed. |          |      |         |        |  |
| Corrective Action: |                                       |          |      |         | Date:  |  |

Paint

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

|                    |                                       |          |      |         |        |  |
|--------------------|---------------------------------------|----------|------|---------|--------|--|
| Contents           | #                                     | Capacity | Type | Tank ID | SE GPS |  |
| CRUDE OIL          | 0                                     |          |      |         | ,      |  |
| Comment:           | Battery Abandoned. Equipment removed. |          |      |         |        |  |
| Corrective Action: |                                       |          |      |         | Date:  |  |

Paint

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|          |  |
|----------|--|
| Type     |  |
| Comment: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Inspected Facilities**

Facility ID: 301973 Type: WELL API Number: 123-30148 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
 Battery Abandoned: All Equipment Removed.  
 COGCC records indicate last production: 03/2017.  
 SI/TA well per variance doc. #401474555. (NOBLE).  
 Yellow LTSI tag for SI/TA status present at wellsite.  
 Locked-Out, Tagged-Out | LOTO.  
 Form 4 Sundry on file, Temporarily Abandoned | TA status date: 12/13/2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/30/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: --

Comment: Prior insp:  
 No record of Brhd test within last 12 months. Refer to Prior Rule 206. Current Rule 207.  
 Submit current Brhd test. Comply w/ Prior Rule 206. Current Rule 207.  
 Contact COGCC Engineering.  
 Corrective Action date: 04/06/2021.

This insp:  
 \* Placed in Comment ONLY status while enforcement protocols being reviewed.

No record of Brhd test within last 12 months. Refer to Rule 207.  
 Submit current Brhd test. Comply w/ Rule 207.  
 Contact COGCC Engineering.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 09/20/2021 at approximately 12:26 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: NOBLE ENERGY INC<br/> Location Name: FAULK USX AB-67N64W /21SESE<br/> Location ID: 410100<br/> Well Name(s):<br/> Faulk USX AB 21-16P.<br/> API: 05-123-30148.<br/> Location County: Weld County, Colorado<br/> Weather: Mostly sunny, dry.</p> <p>While there, I observed:<br/> Well(s): 1: Temporarily Abandoned   TA.<br/> Battery: Abandoned. ALL equipment has been removed.<br/> Abandoned Battery SE corner GPS coordinates: 40.551449 / -104.549991</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs.<br/> (420555, 410100, 410151).<br/> (Well(s): 3: Temporarily Abandoned   TA).</p> <p>Follow-up to Field Inspection Report Doc. #696104139 dated 01/06/2021.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:<br/> 1.) Invalid Emergency number posted at wellsite. Refer to Prior Rule 210.b. (1,2). Current Rule 605.d.<br/> Post valid Emergency number at wellsite. Comply w/ Prior Rule 210.b. (1,2). Current Rule 605.d.<br/> Corrective Action date: 04/06/2021.<br/> * Valid Emergency Number NOW posted at wellsite.<br/> See photos #1, 2.</p> <p>2.) No record of Brhd test within last 12 months. Refer to Prior Rule 206. Current Rule 207.<br/> Submit current Brhd test. Comply w/ Prior Rule 206. Current Rule 207.<br/> Contact COGCC Engineering.<br/> Corrective Action date: 04/06/2021.<br/> * Placed in Comment ONLY status while enforcement protocols being reviewed.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 09/22/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696105037    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538099</a> |