

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2021

Submitted Date:

09/16/2021

Document Number:

701101947

**FIELD INSPECTION FORM**

Loc ID: 315520 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 760 HORIZON DRIVE STE 400  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230977	WELL	PR	12/09/1981	GW	103-08646	DRAGON TRAIL UNIT 1056	PR

**General Comment:**

COGCC Follow Up Inspection Report Summary  
This location is in close proximity of water drainage that runs to Douglas Creek and in a Sensitive Wildlife Habitat (SWH) Details (Mule Deer) Parks & Wildlife (CPW) (Black Bear)  
Follow up to 7/15/2021 inspection # 701101729  
Corrected action item(s)  
• Road was bladed.  
• Battery sign installed at tank battery.  
• Weeds have been addressed.

During this inspection the following compliance issues were observed:  
• Sink hole in shoulder of access road. Just south of DTU 1056 entrance.

The following uncorrected compliance issue were observed:  
• Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Road was bladed.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign installed at tank battery.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911 970-693-6021		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds have been addressed.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<50 BBLs	Open Top		

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

**Venting:**

Yes/No	NO		Date:
Comment:			
Corrective Action:			
Date:			

**Flaring:**

Type		Date:
Comment:		
Corrective Action:		
Date:		

**Inspected Facilities**

Facility ID: 230977 Type: WELL API Number: 103-08646 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Sink hole in shoulder of access road. Just south of DTU 1056 entrance. Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/31/2021

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402814164	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533399</a>
701101954	Inspection 701101947 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533397</a>