

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2021

Submitted Date:

09/23/2021

Document Number:

696105052

FIELD INSPECTION FORM

Loc ID 415324 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415425	WELL	SI	04/01/2017	OW	123-31066	Dillard USX AB 09-15P	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (310218, 415324).
(Well(s): 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel w/ barbed wire.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Shut-down. Protective shed surrounds gas engine.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.580746,-104.546875
Comment:	Centralized Battery serves 2 Location IDs (310218, 415324). Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 415425 Type: WELL API Number: 123-31066 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI
Observed production valves shut.
COGCC records indicate last production: 03/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/14/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____
End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 207.
Submit current Brhd test. Comply w/ Rule 207.
Contact COGCC Engineering.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 09/20/2021 at approximately 13:48 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Dillard USX AB /09-15P Location ID: 415324 Well Name(s): Dillard USX AB 09-15P. API: 05-123-31066. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310218, 415324). (Well(s): 2: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696105050 and/or Location ID #310218 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105053	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5538329