

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 1 loc pic



Photo 2 well heads

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 3 ECD and HOZ Sep



Photo 4 TNK BTRY

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 5 Stained soil around 6-2 well head Flow lines from well head appear to be in the closed position.



Photo 6 Crude oil tank next to public road and bottom half of tank appears to be rusting.

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 7 Cement and trash on location



Photo 8 ECD appears to be taken apart and not functional

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 9 ECD fire arrester on ground



Photo 10 Miscellaneous parts around ECD

Inspection Photos
Location Name: Standley # 8-3, 6-2,5-2
Location ID: 335697



Photo 11 Sales line from separator has 2" bull plug installed



Photo 12 Trash on location.