

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2021

Submitted Date:

09/17/2021

Document Number:

700703245

FIELD INSPECTION FORM

Loc ID 334904	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 12 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260543	WELL	PR	02/01/2008	GW	045-07864	SHAEFFER 31-6 (H-36)	PR
260545	WELL	PR	08/13/2002	GW	045-07866	BJM 31-11 (H-36)	PR
262452	WELL	SI	04/01/2020	GW	045-08030	BENZEL 36-8B(H36)	SI
262453	WELL	PR	02/01/2008	GW	045-08031	BENZEL 36-1 (H36)	PR
262478	WELL	PR	07/19/2006	GW	045-08032	BENZEL 36-9B (H36)	PR
262736	WELL	PR	02/01/2008	GW	045-08051	BJM 31-3C1	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 9/16/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus H36, at Location # 334904 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. A vertical unit separator includes 1 glycol storage tank, approximately 48" x 72" x 191" = 68.02 BBLS each, storage vessel contains no labeling to specify capacity or chemical hazard information.
 2. Lack of bull plugs on load out lines
 3. Lack of battery signage
 4. Location shows signs of lack of stabilization/compaction
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	11/17/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	A vertical unit separator includes 1 glycol storage tank, approximately 48" x 72" x 191" = 68.02 BBLS each, storage vessel contains no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Comply with rule 605.h.	Date:	12/17/2021

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Lack of bull plugs/caps on load out lines		
Corrective Action:	Comply with rule 603.i.	Date:	10/08/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 260543	Type: WELL	API Number: 045-07864	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 260545	Type: WELL	API Number: 045-07866	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 262452	Type: WELL	API Number: 045-08030	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced 3/2020				
Corrective Action:		Date:		
Facility ID: 262453	Type: WELL	API Number: 045-08031	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 262478	Type: WELL	API Number: 045-08032	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 262736	Type: WELL	API Number: 045-08051	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: [Location shows signs of lack of stabilization/compaction](#)Corrective Action: [Install or repair required BMPs](#)

Date: 10/22/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402815436	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5534443
700703255	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5534428