

# Inspection Photos

API: 071-06811

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021

## Inspection Photos



**Photo 1.** Facing northeast at the Lorencito creek crossing. The crossing has been repaired with an additional culvert installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021

## Inspection Photos



**Photo 2.** The disturbed bare soils along the roadside will need to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021

## Inspection Photos



**Photo 3.** Facing toward the culvert outlets which are armored with rock rip/rap.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021

## Inspection Photos



**Photo 4.** Facing at south side of the road at the additional culvert inlet. Disturbed bare shown at red arrow will need to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021

## Inspection Photos



**Photo 5.** Facing back west at the Lorencito stream crossing which was repaired. The disturbed bare soils along the roadside will need to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06811 | Date: 9/23/2021