

Inspection Photos

API: 071-09514

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 9/23/2021

Inspection Photos



Photo 1. Facing southeast along the main road in the canyon. This culvert is filled in with sediment causing stormwater to flow down the side of the road.



Photo 2. Facing northwest at the same culvert outlet which shows stormwater is flowing past the culvert causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 9/23/2021

Inspection Photos



Photo 3. Stormwater is causing a deep erosion channel along the side of the road which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 9/23/2021

Inspection Photos



Photo 4. Further along the road is areas of erosion. There is an exposed pipeline which needs to be covered and protected.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 9/23/2021

Inspection Photos



Photo 5. Another culvert further along the road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 9/23/2021