

Inspection Photos

API: 071-06815

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021

Inspection Photos



Photo 1. Facing north toward the access road. There is a berm and runoff ditch in this area of the road. There is sign stormwater is still directed down the road causing erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021

Inspection Photos



Photo 2. Stormwater directed down the road has caused erosion and degradation of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021

Inspection Photos



Photo 3. A rock rip/rap structure was installed since previous inspection which has contained sediment from the road. This sediment will need to be cleaned out. A sediment trap would be more appropriate in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021

Inspection Photos



Photo 4. Facing south adjacent to the access road. This photo shows the sediment deposition off the road into the adjacent area. The road needs to be stabilized to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021

Inspection Photos



Photo 5. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06815 | Date: 9/23/2021