

# Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021

## Inspection Photos



**Photo 1.** Facing southeast along the main road at the upper part of Lorencito Canyon. There is erosion along the road from recent storm event. Stormwater is bypassing the culvert. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021



## Inspection Photos



**Photo 2.** The culvert along the road are filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00499,-104.83742. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021



## Inspection Photos



**Photo 3.** The side of the road is eroded and not stabilized at Lat/Long:36.99952,-104.83425. This area needs to be resloped, seeded, and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021



## Inspection Photos



**Photo 4.** Further up the road in the canyon is erosion along the roadside with insufficient BMP's.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021



## Inspection Photos



**Photo 5.** There was grading performed along the road. The disturbance along the side of the road shown at red arrow needs to be seeded and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2021